



**METAL  
DEFENDER**  
AFFORDABLE PROFESSIONAL SECURITY



## IMPORTANT! READ BEFORE UNBOXING

Quick start guide for:

### Metal Defender's XLD-H Walk-Through Metal Detector

Steps:

1. Two (2) people are **required** for the initial setup.
2. Carefully unpack your new walk thru metal detector.
3. After unpacking, you should have the following:

One (1)	Right LED Upright/leg
One (1)	Left LED Upright/leg
Two (2)	Power Cords
One (1)	Operation Manual

4. On a flat clean surface, set the Right & Left leg across from each other with the infrared sensors facing inward. The units must be 36 inches apart.
5. Connect a power cord to the outside of each leg. (Make sure each unit is operating on different circuit)

6. Flip the switch under each power cord to turn the legs on.
7. Let the two legs cycle for 30-50 seconds.
8. Set up is now complete and your units are ready to use.

**See your Product Manual for Further details to change security passwords, fine tune sensitivities etc.**

**Product Support:**

**PH 815-290-5354**

**PH: 815-467-6464**

**Fax: 815-467-7420 Email**

**Support@MetalDefender**