



**METAL
DEFENDER**
AFFORDABLE PROFESSIONAL SECURITY

RoHS **FC** **CE**
COMPLIANT



IMPORTANT! READ BEFORE UNBOXING

Quick start guide for:
MD-6(Defense Pro)

Steps:

1. Two (2) people are **required** for the initial setup.
2. Carefully unpack your new walk thru metal detector.
3. After unpacking, you should have the following:

Two (2)	Uprights/legs
One (1)	Head Module
Two (2)	Power Cords
Two (2)	Support Posts
Eight (8)	Bolts
One (1)	Operation Manual

4. Attach head module to the support panels with the pre drilled bolt holes.
5. Identify power input on each leg and make sure it is facing the ground on the outside of the unit.

6. Take the support panel without the head unit installed/ screwed in and using the bolts; secure each leg to the support panel.
7. Take the support panel with the head unit installed from step 4 and secure it to the two legs. (This panel should be facing up with the LCD screens facing the ceiling.
8. With one person on each side carefully stand the unit up. Once the unit is vertical, take the two power cords and connect them as follows. The black power cord will be used on the outside of the legs while the gray power cord will be used to connect the head module to the desired leg you wish power to be ran through with the black cord on the outside.
9. Make sure your unit is at least 3-4 feet away from any metal doors, over ductwork work or other metal objects.

**See your Product Manual for Further
details to change security
passwords, fine tune sensitivities etc.**

Product Support:

PH 815-290-5354

PH: 815-467-6464

Fax: 815-467-7420

Email Support@metaldefender